

Product Change Notification

Document No

PCN-A-1050325

Revision

1.0

PCN Topic:

Change the golden Connector on the Vehicle dock and the Computer part for FM10 / FM08

Introduction:

To improve better performance of external antenna, the Golden Connector on the Vehicle dock of FM10 and FM08 has been changed. The antenna signal has moved into the pogo/ machine pin part. The new dock works only for the new computer part.

Details:



Original Golden Connector on the Vehicle Dock	NEW Golden Connector Design on the Vehicle dock
	

Original Golden Connector on the Computer FM10/FM08	NEW Golden Connector Design on the Computer FM10/FM08
	



Note

The original computer part and the new docking part (or original docking and the new computer part) **cannot cross matched.**

Original Computer part can be paired only with Original Docking part	New Computer part can be paired only with New Docking part
	

Change Date:

03-25-2016

Will be effective from Mar-25-2016

Issued by: Bill Yeh

APPROVE:

[Handwritten signature] MD:

EE:

TE:

PE: